


1P-175-M08-F Breakdown



Description

- A Head Assembly
- B O-ring
- C Replacement Element

Part

- WIL-065
- N32-95-256
- 1P-175

Description

- D Bowl Ring (only)
- E Bowl Assembly w/ Drain
- F Auto Drain

Part

- WIL-013
- N34-15-178
- N32-95-979



(800) 521-9200



www.driair.com | www.rti-pbe.com



@RTiPBE



@rti_pbe

